


Mounting Instruction mSWM

INTRODUCTION

MTX LED mSWM Lamp –Mounting with adapter.

Each set of lamp include 4 pcs. of screws
St.4.2x25, for lamp installing.



It is necessary to drill 4 pcs. of holes with diameter $\Phi 3,5\text{mm}$, in spacing 76mm x 76mm, on wall of housing.

After connection mounting and inserting of plug to socket it is necessary to screw lamp by using 4 pcs. of screws St.4.2x25.

Torque of tightening for screws St.4.2x25 is 1,2Nm.

NO.	Description	Qty.
1	Lamp	1
2	Screw St.4.2x25	4
3	Housing	1

NECESSARY TOOLS



Drilling bit $\Phi 3,5\text{mm}$



Screwdriver Torx T20



Crimper: CA-5D12

Contact:



+40 748 751 465

sales@mtxledsolutions.com

www.mtxledsolutions.com


MTX LED reserves the right to make technical changes without prior notice.

Copyright © MTX LED 11.09.2018 VA02

Mounting Instruction mSWM

Mounting of connection on feeding cable.

Amphenol connection is included in set. Fitter of lamp has to install socket and plug on both ends of feeding cable, (on lamp side and car side). Pins on cable have to be crimped with crimper CA-5D12.



NO.	Description	Qty.
1	Lamp	1
2	Screw St.4.2x25	4
3	Housing	1
4	Feeding cable of Lamp	1
5	Socket	1
6	Plug	1
7	Feeding cable on car side.	1

Contact:



+40 748 751 465

sales@mtxledsolutions.com

www.mtxledsolutions.com


MTX LED reserves the right to make technical changes without prior notice.

Copyright © MTX LED 11.09.2018 VA02

Mounting Instruction mSWM

Mounting of socket on cable -lamp side

For mounting of socket it is necessary to remove insulation from cables on length 5mm. Solder with tin cable ends. To crimp with crimper CA-5D12 both pins on cable ends. To remove locking Wedge from socket case. Next step it is inserting of both cables to socket case. As last step fitter has to insert Locking Wedge back into socket case.



NO.	Description	Qty.
1	Case of Socket	1
2	Locking Wedge	1
3	Male Pins	2

Crimped cable Pin:



Contact:



+40 748 751 465

sales@mtxledsolutions.com

www.mtxledsolutions.com


MTX LED reserves the right to make technical changes without prior notice.

Copyright © MTX LED 11.09.2018 VA02

Mounting Instruction mSWM

Mounting of plug on cable -car side.

For mounting of plug it is necessary to remove insulation from cables on length 5mm. Solder with tin cable ends. To crimp with crimper CA-5D12 both pins on cable ends. To remove Locking Wedge from plug case. Next step it is inserting of both cables with pins to plug case. As last step fitter has to insert Locking Wedge back into plug case.



NO.	Description	Qty.
1	Case of Plug	1
2	Pins Locking Wedge	1
3	Female Pins	2

Contact:



+40 748 751 465

sales@mtxledsolutions.com

www.mtxledsolutions.com

MTX LED reserves the right to make technical changes without prior notice.

Copyright © MTX LED 11.09.2018 VA02